

# SAFETY ALERT

<b>INCIDENT</b>	Tipping trailer made contact with overhead power
<b>SUBJECT</b>	Mobile Plant/Live Services
<b>INCIDENT DATE</b>	19 March 2021
<b>BUSINESS UNIT</b>	Infrastructure – NX2 Puhoi to Warkworth Project

## WHAT HAPPENED?

At approximately 1.00 pm on 19 March 2021 a T&T tipping topsoil has driven forward with the rear bin raised making contact with a 240 volt overhead power cable.

The area was frozen and the driver instructed to remain in the cab until safe to exit. Vector attended the scene and isolated the service making the area safe, the driver could now safely exit the cab.

Line indicates location of overhead service



## IMPORTANT REMINDER FOR ALL OF US (pre-investigation)

- Plan your works to eliminate the need to work in the vicinity of overhead services
- No works within 6.4 meters of overhead services unless and approved permit is in place.
- All permit requirements must be in place prior to works commencing including service asset owner’s specific requirements and safety spotters.
- All overhead services must be delineated, and heights signposted
- No work on live services

## FOR MORE INFORMATION, PLEASE CONTACT

Robert Jones, Project Director  
 Robert.Jones@nx2.co.nz, +64 27 217 5344