

INCIDENT ALERT

LOCATION:	CONCRETE PRODUCTS	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	08/08/2019 15:34:42
SUB ACTIVITY:	N/A	INCIDENT No:	01521

TITLE

Operator sustains cement/lime burns cleaning mixer

COUNTRY OF ORIGIN

United Kingdom

ACCIDENT / INCIDENT DETAILS

Following a breakdown, there was a requirement for operatives to enter and clean out a mixer. The process created an amount of dust and the atmosphere was hot and humid.

One of the operators undertaking the task was wearing two-piece workwear (trousers and top). Following the clean-down the operative experienced discomfort to his lower back. The injuries were later diagnosed as lime burns, which he sustained from the lime dust reacting with sweat on his body and the general humidity within the area.

ACCIDENT / INCIDENT IMAGES

LEARNING POINTS / ACTIONS TAKEN

- For any cleaning duties that generate dust of a specific hazardous nature (refer to Safety Data Sheets / COSHH risk assessments to identify these risks), operatives should be issued with full-piece workwear / coveralls to protect them
- Operatives, who undertake duties that expose them to hazardous duties/chemicals/oils/ sensitisers and similar, should be encouraged to utilise shower facilities at the site to remove any contamination quickly
- All such tasks should have suitable risk assessments and standard operating procedures.

LEARNING POINTS / ACTIONS IMAGES