

METAL/NONMETAL Serious Accident Alert

Surface – Crushed & Broken Stone – On June 16, 2018, a mechanic fell 10 feet from a portable cone crusher. The mechanic struck his head on the crusher before landing on the ground.



Best Practices

- Establish and discuss safe work procedures before beginning work. Identify and control all hazards associated with the work to be performed and ensure a means of safe access is available when working on equipment.
- Ensure proper fall protection is used when miners are exposed to a fall hazard.
- Train miners in the use and care of fall protection equipment. Provide ladders, mechanical lifts, and/or other safe access means when a safe access is not available. Ensure secure footing in all work areas.



www.msha.gov
askmsha@dol.gov
Twitter: @MSHA_DOL

Report Accidents &
Hazardous Conditions
1-800-746-1553