DECISION BLOCKING MARBLE QUARRY

MOBILE CRUSHING CONTRACTS COMPLETE AVOCA BUSINESS

WOLF DOUBLES REVENUE ON RECORD TUNGSTEN PRICE

INSIDE RESOURCES Monday 12 March, 2018

- ICPMS
 - Environ ntal Sampling & Analysis
- · Coal Analysis
- State of the Art



Advertisement

Driver hurt in Northland quarry crash

A contractor was air-lifted to Auckland hospital after the Moxy he was driving rolled down a hill and into a bank at

Emergency services were called to Parker Lime Co in

"Of course, when he went over the drain the back tipped over on its side, but the front

He told *Inside Resources* the subcontractor had serious lower lumbar injuries.

Bowmar said the drain was almost 2 metres deep and about 1.5 metres wide. The drain was filled in by a digger to get the man out without doing him any more harm.

Because of the thick steel of the Moxy, Bowmar says the crew unbolted the door to get

onsite to do stripping work at the quarry. He understands the man is recovering well.

MinEx chief executive Wayne Scott says it is always disappointing to hear of an incident in the extractives sector.

disposal, so I will be trying to contact the company to see if we can offer any assistance."

Factfile information Resource Kaiwaka

Find out more...

A WorkSafe spokesperson says the agency was notified of an incident at Parker Lime earlier this week in which a truck rolled. WorkSafe will not be investigating the matter.

Rate this article:

Topics: quarry quarrying incident accident injury health and safety WorkSafe

Organisation: WorkSafe New Zealand NZ Fire Service

Factfiles

Resource factfile Kaiwaka

Printer-friendly version

Related content

WorkSafe fills leadership roles

Concrete NZ courses covers Health and Safety Act

Incident reporting to focus on near misses - MinEx

Family of man killed by machine to get \$85k

NZ Workplace Health and Safety Awards open for entry

Cameron Massey - Fri, 09 Mar 2018

a Northland quarry this week.

Kaiwaka on Monday evening.

Wellsford Fire Service chief fire officer John Bowman believes mechanical failure caused the 30-tonne Moxy to careen about 150 metres down a hill into a drain.

went through at a bit of an angle and yeah, he was compressed.

"We got the rescue helicopter and he was taken to Auckland hospital."

Condition

Bowmar said the man, who he thought was in his 30s, was an outside contractor

"We don't have all the facts at our

Police are investigating the crash.

No votes yet

Recent comments Care urged with new marine sanctuaries (1)

Totally agree with your sentiments Mike. Yes Parliament can pass laws but it's a fundamental tenet of good law...

Find out more

GLOBAL

TRACTORS LTD

Ph +64 3 423 9289

Brigid McArthur

Climate change plan unworkable (1)

Buller District Council decided to heat Buller's new pool and sports complex with electricity. This has proved to be a... Neal Clementson

NZ lags world on tungsten opportunity explorer (1)

Good work Gary Gray !!

MinEx says no silicosis risk for residents (2)

Thanks Murray. The press release has gone too general media so hopefully some will pick it up. Wayne Scott

MinEx says no silicosis risk for residents (2)

This is a great article, but nothing that we didn't already know. Pleased that Wayne has met with Dr Humphrey as it is... Murray Francis

Search

Enter keywords...

Search

Featured content

Call on NZ to protect supply of critical minerals

Bernie Napp

New Zealand should join the US and Europe in safeguarding the supply of "critical minerals", necessary for achieving a zero-carbon future, GNS Science says.



The Crown research institute was commenting on separate initiatives launched this year in the US, the European Union, and in Sweden to protect the supply chains of critical minerals from scarcity, disruption, and geopolitical..

Read more

NZ lags world on tungsten opportunity explorer

Bernie Napp

New Zealand is failing to tap into a fastevolving world market for tungsten, an explorer of the technology metal says.



Global demand for tungsten could outstrip supply this year, with China closing mines. and growing concern over "conflict minerals", while prices remain steady.

Read more

More articles

Advertisement



Advertisement



Advertisement

Interviews

EXECUTIVE INTERVIEW: Mark Pizey - outgoing chief inspector extractives, WorkSafe Bernie Napp



After 21 months in the role, Mark Pizey reflects on his time at

WorkSafe, offers parting thoughts...

- EXECUTIVE INTERVIEW 3: Mick Wilkes - chief executive officer, OceanaGold
- EXECUTIVE INTERVIEW: Peter Silcock - chief executive, Civil Contractors NZ
- EXECUTIVE INTERVIEW: Hon Judith Collins – Minister of Energy and Resources
- EXECUTIVE INTERVIEW 2: Richard Tacon – chief executive officer, Bathurst Resources
- EXECUTIVE INTERVIEW: Robert Jones – Chief Executive Officer, Fulton Hogan NZ



Energy Resource Factfile

GFA 42012 (Louis Creek- Gfa 12)

Gold fossicking area



View full listing

View all resources

Organisation Factfile

Elect Mining

Ownership Major shareholders: Orient Exploration 45.4%, Michael Lance 45.4%

Description Minerals explorer · Gold explorer

Operating resources Butlers (Elect), Goldsborough

Non- Canvastown , German Gully, MEP operating 55133, MEP 56908 (Canvastown), resources MEP 57533 (Kumara Flat), more...

View full listing

View all organisations

Popular Recent

Today

Top rated

- Sage declares conflict of interest over hydro scheme
- Court told Bathurst delaying Escarpment payments
- Fletcher chair to resign as losses widen to \$660 min
- Call on NZ to protect supply of critical minerals
- Fulton Hogan compromised on trucks for Clevedon expansion
- Clevedon quarry extension granted
- Fletcher clarifies plan for Building and Interiors
- Legal experts on Sage and Te Kuha

more

Organisation cloud

Bathurst Resources Chatham Rock
Phosphate Environmental Protection Authority
Fletcher Building Fulton Hogan Government
MinEx New Zealand Petroleum & Minerals
NZTA OceanaGold Solid Energy
WorkSafe

More

Keyword cloud

aggregates coal consents construction contracting environment exploration financials gold health and safety infrastructure iron ore

minerals mining permits quarrying regulation Roading seabed mining West Coast

More