

SAFETY ALERT		
Department: MICO - Fixed Plant		
Location: 20/L Crib room Car Parking Area		
Incident Date: 14/03/2021	Incident Time: 20.04	Incident Number: INC-0161506
Safety Alert Title: Operator has injured right leg		
Fatal Hazard: 4. Mobile Equipment	For "Other" describe:	
Process Safety Management related Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	The incident involved: <input checked="" type="checkbox"/> Employee <input type="checkbox"/> Contractor:	
Brief Description		
<p>An Operator was loading gear into the back of a Toyota. Another operator in the Toyota behind him was carrying out his pre-start and has taken his foot off the clutch at the same time as turning the key off, causing the Toyota to lurch forward, trapping the operators right knee between the rear step of the front Toyota and the bull bar of the other Toyota.</p> <p>SIBS Brakes were applied at the time.</p>		
Key Learnings		
<ol style="list-style-type: none"> 1. Carparks are not to be used as storage areas. 2. When vehicles are parked in an underground situation wheels are to be turned into the walls. 		
Corrective and Preventative Actions		
<ol style="list-style-type: none"> 1. Review housekeeping of the carpark and move unnecessary materials to appropriate storage areas to allow for safe vehicle parking. 2. Review the signage in the carpark and replace signs as required to ensure the area is kept as a designated parking area. 3. Reiterate to all personnel C-MICO-MINE-PRO-General Driving Underground (Road Rules) (370101) Section 3.8.1 General Rules. 		
For further information contact		
Name: Daniel Breen		Title: Supt. Fixed Plant Maintenance & Operations
Phone: 4744 2081		Email: daniel.breen@glencore.com.au
Approved by		
Name: David Bartolo		Title: Manager Fixed Plant Maintenance
Signature: 		Date: 01/04/2021