

Fatality Alert

MINE FATALITY – On August 3, 2021, a miner was run over by a customer tractor-trailer while walking to his normal work area.



Best Practices

- **Assure adequate illumination** sufficient to provide safe working conditions.
- **Communicate with mobile equipment operators and make eye contact to ensure they acknowledge your presence.** Be aware of the location and traffic patterns of mobile equipment in your work area.
- **Wear high visibility clothing** when working around mobile equipment.
- **Wear strobe lights** near mobile equipment.
- **Assure traffic controls provide for safe movement of mobile equipment and are followed.** Operate mobile equipment at reduced speeds in work areas.
- **Stay clear of normal paths of travel for mobile equipment** and train all persons to recognize work place hazards.

This is the 23rd fatality reported in 2021, and the ninth classified as “Powered Haulage.”

The information provided in this notice is based on preliminary data only. It does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553

[msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)